



Hotline Guide

- 👤 Hotline Hosts: Nutz & Boltz
- 🎙️ Producer: Doctor Jordan
- 👤 Correspondent: David Deal
- 👤 Detroit Reporter: Duncan Galbraith
- 🎛️ Studio Engineer: Dave Benjamin
- 🗣️ Media Director: Jim Cochran

The Nutz & Boltz weekly *Auto Motive Hotline* brings new car-care and lasting vehicle tips, the latest safety & travel info, answers to automotive questions, and helpful info about other vehicular concerns.

Motor Watch

🕒 Hotline Program Date: 08.11.07



👤 *Stacy Nicholson* (www.cnrinsurance.com) > Hidden devaluation and how it affects your car value, deductible costs, and how an insurance agent can help you understand insurance surcharge thresholds.

🕒 *Motor Minute*® > Lifesaving resources aren't made available to most crash victims.

👤 Bump— Beatles: "Sergeant Pepper"

BREAK :15 Fritz Car Care 410-727-7531; International Auto Repair 410-944-6850; Walt Eger's Service 410-519-8445

👤 Bump— Back Street Boys

👤 *Don Staples* (www.millersvilleautocenter.com) > Don is manager of Environmental Auto Service in Millersville and shares some of his automotive repair experiences from being in the repair service industry for 38 years.

🕒 *Motor Minute*® > Color-shifting paints on new cars actually change colors as they drive by and the appeal of color-shifting is becoming increasingly popular.

👤 Bump— Yoko Ono: "Don't Be Scared"

BREAK :30 Auto Sense 410-761-1599; Admiral Tire & Auto 410-741-0400, Redds Auto 410-268-7789

👤 Bump— Chicago

👤 *Jim (Mayo MD): 2003 Mazda Tribute* > *Changing the transmission fluid to synthetic.*

🕒 *Motor Minute*® > Blind pedestrians want hybrid cars to emit more noise.

👤 Bump— Eric Clapton

BREAK :45 Severna Park Auto Body 410-987-9493, Redline Oil 800-624-7958

👤 Bump— Lennon: "I'm Losing It"

🚑 *Safety Minute* > Airbags are the cause of foot and ankle injuries.

?!? *Know It All* > After machining brake rotors, you need to prep them for installation by sanding the machined surface lightly with sand paper. *True or False?*

🔧 *Car Care Tip* > An engine that had its combustion chamber or injectors cleaned, may have problems.

✉️ *Mail Bag question: Joseph (Youngstown OH)* > 1997 Buick LeSabre 3.8L with near 200k: I'm getting a trouble code for bank one O2 sensor. The sensors are original. Which cylinder bank is bank "one"?

👂 *Sound Byte from the movie soundtrack: Smoke Signals: "Traffic Report"*

Nutz & Boltz Theme Closing Music

👂 MotorWatch is an indefatigable protector of the American public's right to have safe, defect-free vehicles.

👂 The MotorWatch is a non-profit organization funded membership dues and contributions. For more information about becoming a member and member benefits, call 1-410-0900 or see www.motorwatch.com

👂 MotorWatch has been providing help for motorists since our 1st informational car-care program was broadcast in 1971.

👂 The MotorWatch Hotline has continually been broadcast since 1986, and on the internet since 1997.

👂 The MotorWatch hotline is broadcast live every week on WBI S. Certain portions may be pre-recorded or edited.